



Spare Part No.	Part No.	Part Name	Easy Damage	Part Picture
ID7108-SP-D.C	TS00001735	Drill chuck10mm(with key)No		
ID7108-SP-1	AA004000080	Left-threaded screw M6*25No		
ID7108-SP-2	AA004000002	Chuck(13mm) No Output		
ID7108-SP-3	DD00003609	ShaftNo Ball 3No circlip 12No		
ID7108-SP-4	DD00003610			
ID7108-SP-6	AA004000048			
ID7108-SP-7	DD00003611	Gear	No	
ID7108-SP-8	AA004000053	Circlip 10	No	
ID7108-SP-9	DD00003612	Spring	No	
ID7108-SP-10	DD00003613	Whisht Lapact Block	No	
ID7108-SP-12	DD00003614	Oil shieldNo Support No Bolt		
ID7108-SP-13	DD00003615	M4x6No Screw ST4.2*16No		
ID7108-SP-14	DD00003616	founction leverNo Slip Plate		
ID7108-SP-15	AA004000063	Drill/Impact SelectNo Spring No		
ID7108-SP-16	DD00003617	Carbon brush holderNo		
ID7108-SP-17	DD00003618			
ID7108-SP-18	AA004000068			
ID7108-SP-19	DD00003065			
ID7108-SP-20	DD00003619	Carbon BrushNo		
ID7108-SP-22	DD00003620	Arm at ure	No	
ID7108-SP-23	DD00003621	BEARING 607	No	
ID7108-SP-24	DD00003622	Stator	No	
ID7108-SP-25	DD00003623	I abel	No	
ID7108-SP-26/28	DD00003624	left&right Housing	No	

ID7108-SP-29	DD00003625	Switch	No	
ID7108-SP-30	AA004000073	Cord protector	No	
ID7108-SP-31	DD00003074	Power cord 2M	No	
ID7108-SP-32	DD00003075	Screw M8x100	No	
ID7108-SP-33	DD00003076	hose clamp	No	
ID7108-SP-34	DD00006443	Side handle	No	
ID7108-SP-35	DD00003626	Scale	No	

